



LISTING REPORT/INSPECTION PROCEDURE

Xciel Inc.
REPORT NO.: 619559/01

Page 1 of 14
Issued: 28 July 2015
Revised: None

620 Old Peachtree Road, Suwanee, GA 30024 USA (770) 570-1800

Project No. 3780967

A representative sample of the product covered by this report has been evaluated and found to comply with the applicable requirements of the Standard for Nonincendive Electrical Equipment for Use in Class I and II, Division 2 and Class III, Divisions 1 and 2 Hazardous (Classified) Locations (ISA 12.12.01-2013 Rev. June 3, 2013) and the Standard for Non-incendive Electrical Equipment for Use in Class I, Division 2 Hazardous Locations (CSA C22.2 No. 213-M1987 (R2008) +G1).

Issuing Laboratory	Consumer Testing Services, a division of SGS North America, Inc.
Address.....	620 Old Peachtree Road, Suite 100 Suwanee, GA 30024 USA
Applicant	Xciel Inc.
Address.....	5554 South Peek Rd. Katy, TX 77450
Contact Details	Xavier Balourdet Phone: 281-220-7305 Email: Xavier@xciel.com
Manufacturer 1	Xciel Inc.
Address.....	19830 F.M. 1093 Rd., Suite 2001 Richmond, TX 77407
Contact Details	Xavier Balourdet Phone: 281-220-7305 Email: Xavier@xciel.com



LISTING REPORT/INSPECTION PROCEDURE

Xciel Inc.
REPORT NO.: 619559/01

Page 2 of 14
Issued: 28 July 2015
Revised: None

Product Type	CID2 Rugged Surface Pro 3 Windows 8 Tablet
Trade Mark	N/A
Product description	The product covered is a rugged enclosure that is for use with a Surface Pro 3 tablet. The assembly requires a nylon sleeve for added mechanical protection. The product is for outdoor use. When used in a hazardous location, enclosure and nylon sleeve must be present and not removed.
Model Number(s)	XCPro3
Model Differences	N/A
Electrical Ratings	7.4VDC, 5676mAh Battery
Hazardous Location Ratings	Class I, Division 2, Group A- D, T6, IP65
Other Ratings	N/A
Accessories	N/A
Testing Laboratory	Consumer Testing Services, A division of SGS North America, Inc.
Address	620 Old Peachtree Road, Suwanee, GA 30024 USA
Date of receipt of test item	6/16/15
Date(s) of performance of tests	6/16/15
Conditions of Acceptability	Nylon cover from Item 2 is required at all times.



LISTING REPORT/INSPECTION PROCEDURE

Xciel Inc.
REPORT NO.: 619559/01

Page 14 of 14
Issued: 28 July 2015
Revised: None

CONCLUSION

Samples of the products covered by this Report have been found to comply with the applicable requirements of the Standard for Nonincendive Electrical Equipment for Use in Class I and II, Division 2 and Class III, Divisions 1 and 2 Hazardous (Classified) Locations (ISA 12.12.01-2013 Rev. June 3, 2013) and the Standard for Non-incendive Electrical Equipment for Use in Class I, Division 2 Hazardous Locations (CSA C22.2 No. 213-M1987 (R2008) +G11).

Report Prepared by:

A handwritten signature in black ink, appearing to read 'Andrew Delisle'.

Andrew Delisle
Project Engineer

Report Reviewed by:

A handwritten signature in black ink, appearing to read 'Jedd Smith'.

Jedd Smith
Sr. Project Engineer